

# SIMATIC-Ka

Interface		Canon H	Vstupy		
	1	2	2	I 0.0	RK A
	3	3	4	I 0.1	RK B
+5V	7	4		I 0.2	
0V	5	1	30	I 0.3	SAC
stínění	5		18	I 0.4	urychlení
			38	I 0.5	W
			25	I 0.6	LU
			24	I 0.7	PU
			31	I 1.0	UAC
			34	I 1.1	POB
			39	I 1.2	ZPS
			37	I 1.3	PPS
			33	I 1.4	rychloposun vzad
			32	I 1.5	rychloposun vpřed
			Výstupy		
				Q 0.0	
				Q 0.1	
				Q 0.2	
				Q 0.3	
				Q 0.4	
			7	Q 0.5	ruční
			9	Q 0.6	KAC
			12	Q 0.7	X>WSP
			10	Q1.0	Z stop
			11	Q1.1	Res.

  

zdroj	
+24V	14
+24V	8
0V	6
0V	16

  

+24V	L+
0V	M_1M

**Simatic 15.5  
RELÉOVÝ**

VUES Brno

		Canon X			
	9	2	12	I 4.0	Enkodér KM A
	11	3	10	I 4.1	Enkodér KM B
+5V	13	4			
0V	15	1			
	stínění	5			

  

M752	
PUL-	4 2kO SB Q 4.0 KM Pulse
DIR-	1 2kO SB Q 4.1 KM Direction
+24V	++ 2
+24V	++ 3

tisk 11.08.15 16:31